

BAYSIDE SURVEYING

**11765 HWY 101 South
Tillamook, Oregon 97141**

**Terry L. Jones
503-842-5551
Fax 503-842-5552**

October 2002

REWITNESS
SECTION CORNER COMMON TO SECTIONS 26, 27, 34 & 35
TOWNSHIP 2 SOUTH, RANGE 8 WEST

I found:

40" Cedar stump (9" shell with 14" burnt out center) bears S51°E
16.5' (GLO 14" Cedar S51°E 25 lks);

No evidence of other 3 GLO bearing trees;

Ridge runs S75°E is South 66' (GLO Ridge runs S75°E is 1.00 chain
South); Canyon runs East is North 198' (GLO Canyon runs East is North
3.00 chain); Creek runs S60°E is 820' East (GLO creek runs S60°E is
13.50 chains East)

I set 1½" X 40" galvanized iron pipe with SODF brass cap stamped
"T2SR8W S26 S27 S34 S35 2002 LS2507", 39" in ground, on steep
Northeast slope.

From which:

Set steel posts South 4' and East 4', and 4 New BTs as follows:

15" Douglas Fir scribed "T2S R8W S26 BT" bears N32°E 14.8' to brass
nail and washer stamped "LS2507" between the B & T;

11" Douglas Fir scribed "T2S R8W S27 BT" bears N51°W 16.25' to brass
nail and washer stamped "LS2507" between the B & T;

14" Douglas Fir scribed "T2S R8W S34 BT" bears S71°W 16.8' to brass
nail and washer stamped "LS2507" between the B & T;

15" Douglas Fir scribed "T2S R8W S35 BT" bears S23°E 16.20' to brass
nail and washer stamped "LS2507" between the B & T;

In the presence of Terry Jones, Dallas Esplin

