

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 3, 4, 33 and 34
T. 1 & 2S, R. 8W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 16 x 12 x 7" (now missing, area recently logged, found 2" x 48" galvanized iron pipe out of place) from which a:

10" Hemlock bears N56°W 47 lks.; now a rotted stump (42 lks.)

12" Hemlock bears N63°E 22 lks.; now 22" uproot, portion of scribes visible on rotted face.

10" Hemlock bears S51°E 42 lks.; now 26" stump (28 lks.) scribes T8S R2W S3 visible.

14" Hemlock bears S44°W 28 lks.; now 32" stub 15' high (47 lks) scribes W S4 visible.

RESTORATION by Jack L. Sheppard 1947

2" iron pipe set (found, see above)

RESTORED

Reset above 2" x 48" galvanized iron pipe, 40 inches in ground, in mound of stone, and from which a:

13" Hemlock bears N20°E 23.7 ft.; scribed T1S R8W S34 BT RS359.

8" Hemlock bears N22°W 43.8 ft.; scribed T1S R8W S33 BT.

15" Hemlock bears S2°E 55.4 ft.; scribed T2S R8W S3 BT.

10" Hemlock bears S46°W 10.8 ft.; scribed T2S R8W S4 BT.


Set 4 x 4 x 72" white painted Cedar post 1' NW of pipe.

Oregon State Board of Forestry metal location poster on 10"

Hemlock BT. Also poster on 4 x 4 x 72" white painted Cedar post 164' E on W side of Gold Peak Road.

Dated October 25, 1957

Restored by David Steenson, Engineering Aide, under my direction.



Present and witnessed by Clarence Skog