

NOTICE OF REPAIR OF SECTION CORNER Sec. 17-18-19-20 T3N R10W

This corner was a cedar post about 5x5" x 3 feet long, scribed with the section numbers on each side, set in mound of rocks, when I saw it in 1947 and 1950. The cedar post is now rotted off and lying down. In its place I set a pneumatic drill "Bull Point", a hexagon steel rod, 1" x 24". A bushy 26" Fir bears N 70* W about 60 feet. The corner is uphill about 8 feet from center line of the Coast Guard telephone line, about midway between two poles which are about 140 feet apart; it is on the sidehill, about 140 feet easterly northerly from Highway 101.

W. A. Markham, Reg. Engr. No. 1842

October 6, 1961.

W. A. Markham

494

Book I