RESTORATION OF THE QUARTER CORNER COMMON TO SECTIONS 20 AND 21, T3N, R9W, W.M.

At the corner I find the 1-1/2" iron pipe with 3" bronze cap, top 2" above ground, as reported by Harold Russell in Tillamook County Re-Witness Book 5, Page 42. Russell's B.T.'s bear as follows: the 25" hemlock at S06°30'E 19.8 ft. is now a 36" hemlock that bears S06°30'E 18.74 ft. to an 8" spike I set in notch at base of fully overgrown face. The 16" hemlock at S33°W 44.6 ft. is now a 23" hemlock that bears S33°W 43.54 ft. to an 8" spike I set in notch at base of fully overgrown face. Set a 6' steel fence post with location tag 2' east of corner.

Note: Bearings reported to bearing trees are hand compass bearings using a declination of 21 1/2° east.

TW.00.4 CO.

NOV 18 1999

VEYORS OFFI

Field work by A. Hofmann & R. Erickson on 7/22/99 Field examined and approved by K. Foeste, LS 849, on 11/8/99

Karl F. Foeste 361 S.W. Main Ct. Warrenton OR 97146

REGISTERED PROFESSIONAL LAND SURVEYOR

> OREGÓN JULY 12, 1998 KARL F¢ FOESTE 0849

Renews 1/1/2000