

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 5	TOWNSHIP 3 South	RANGE 10 West
COUNTY: Tillamook		DATE: 4-24-09
CORNER DESIGNATION: The One-Quarter Corner common to Sections 5 and 8.		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
<input type="checkbox"/> Referenced Out		
Previous Rewitnesses, Restorations and Surveys, etc: BLM Field Notes Volume: OR-R0337 Page 322 (1890), BLM Field Notes Volume: OR-R0545 Page 136 (1933), Rewitness Card #592 (1963); Map B-1226 A&B, Tillamook County Survey Records.		
Found Monument(s) and Accessories (Condition & Source): Found a 2-1/2" brass cap leaning due to blown over trees, straightened monument and placed a rock collar and 120 pounds of concrete around the monument. The monument is stamped as shown hereon. Conventionally field tied the one-quarter corner monument using GPS established control points. The Oregon North Zone State Plane in NAD 83/91 grid coordinate position for the monument is N = 626150.599, E = 7319265.710, U.S. Feet. Found an orange carsonite plastic post North 3.0' of monument. Found a 48" diameter Spruce tree with healed face and metal bearing tree tag (1933 GLO survey calls the tree a 30" diameter Hemlock tree which bears N 60° W 61 lks.) at record position. Did not find the 24" diameter Hemlock tree marked by the GLO in 1933. Found a 34" diameter Hemlock tree with scribing partially visible (was a 30" diameter Hemlock marked in 1963, see Rewitness Card #592), at record position. Found a U.S.D.A. Forest Service Reference monument stamped "RM ¼ S5 LS1084 1986 S00-19W 39.0 FT" at a grid bearing of South 03° 08' 03" West 38.96'. This reference monument appears to be located in an area of unstable landslide material. It is leaning downhill amongst several large trees that have blown over.		
Monument Set (Procedures and Description): Not applicable.	Sketch of Found Monument:	
New accessories set: Set a hat section post South 3.0' from the monument.		
New Bearing Trees set: No new bearing trees set.		
Location & Comments: Corner is located on a steep Northeasterly facing slope and 100 feet East of a ridge.		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL
Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor		
Notes:		
Witnesses: Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor. Michael R. Rice, L.S.I. 16723, Survey Technician		RENEWAL DATE: 06-30-09