

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: The Southeast Corner of Section 32; the Northeast of Section 5	TOWNSHIPS 1 South and 2 South	RANGE 9 West
COUNTY: Tillamook		DATE: 04-21-11
CORNER DESIGNATION: The Section corner common to Sections 32, and 33, Township 1 South, Range 9 West and Sections 5 and 4, Township 2 South, Range 9 West, W.M., Tillamook County, Oregon.		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
		<input type="checkbox"/> Referenced Out
Previous Rewitnesses, Restorations and Surveys, etc.: BLM Field Notes Volume: OR-R0053 Page 0111; Tillamook County GLO Book Section 1SR9, Pg. 49 (1857); Rewitness Book 5, Page 151 (1971); Rewitness Card number 257 and 258 (1974); Map B-1044, Map B-293; Map B-178; Map A-824; Map A-8308; Map A-3266; Map A-3175; Map A-3961; Map A-8350; Map P-191; Tillamook County Survey Records.		
Found Monument(s) and Accessories (Condition & Source): Found a 3" diameter Tillamook County Brass cap, upright, 0.30' below the surface with a destroyed cap. Replaced cap as described below.		
Monument Set (Procedures and Description): I referenced out the center of the found 3" brass cap and then proceeded to remove the destroyed brass cap and pipe. Set a ten inch diameter cast iron monument box at corner monument position in which a 2" diameter Tillamook County Surveyor Brass Disk on a 6" long piece of 3/4" iron pipe was set in 120 pounds of concrete. The disk is stamped as shown hereon.	Sketch of Set Monument:	
Found Accessories - All field measurements were taken using a Topcon GPT 3005 Total Station occupying the corner monument. Found the 84" Hat Section post leaning and out of position. Placed back to record position at (East 19.5') ¹ . Found power pole #331100 with a scribed triangle in pole (N89°E 39.37') ¹ and reset a nail in the center of the triangle which bears N89°E 39.55'. Found pole #041800 with a scribed triangle in pole (S44°E 23.60') ² which bears S44°E 23.67'. Found Northeast corner of concrete house foundation (S65° 30'E 97.60') ¹ at record position Some of the distances to the power poles have changed due to the tension of the guy anchors. () ¹ - Record values from Rewitness Card #257 () ² - Record values from Rewitness Book 5, Page 151		
New Bearing Trees Set and/or Accessories Set: There are no trees in this area to mark as bearing trees. Center of nut on water standpipe which bears South 38° 50' West 22.47'. Southwest corner of concrete house foundation which bears South 37° 30' East 87.25'. Single-occupation GPS observation - Northing = 661670.158, Easting = 7354366.536, U.S. survey foot; '83/'91 NAD Oregon North Zone, State Plane Coordinate.		
Location & Comments: This corner is located in a gravel pullout and driveway area on McCormick Loop Road.		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141	SURVEYOR'S SEAL	
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor		
Notes: Digital images were taken of the monument, and the existing and new accessories.		
Witness: Danny R. McNutt, PLS 49230, Tillamook County Surveyor; Michael R. Rice, L.S.I. 16723, Survey Technician		

