

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 18	TOWNSHIP: 1 South	RANGE: 9 West
COUNTY: Tillamook		DATE: 02/2022
CORNER DESIGNATION: Section Corner Common to Sections 17, 18, 19 and 20, 1 South, 9 West, Willamette Meridian.		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input type="checkbox"/> Reset at surface
		<input type="checkbox"/> Referenced Out

Previous Rewitnesses, Restorations and Surveys, etc...

A-612 (1955), A-1535 (1968), A-2176 (1971), A-2500 (1973), A-2505 (1973), A-2509 (1973), A-3333 (1977), A-5301 (1985), A-5945 (1990), A-6490 (1992), A-8176 (2007), B-160 (1949), B-227 (1911), B-535 (1967), B-1364 (1989), B-1610 (1992), B-1794 (1994), B-2151 (1997), B-2810 (2004), B-3288 (2009), B-3578 (2013), P-117 (1993), P-439 (1997), P-534 (1999), P-1075 (2016), HAYES "E" PG. 34 (1881), REWITNESS BK.10 PG. 6 (1887), S3 PG. 236, REWITNESS BOOK 4 PG. 54 (1949), Rewitness card #206 (1973)

Previous Rewitnesses, Restorations and Surveys, etc...

In 1857 the Section corner was monumented by a wood post by the General land Survey Office from which 4 accessories were set. In 1887 (Rewitness bk. 10 pg. 5-6) R. R. Hayes renews corner to section by setting post for corner from which he sets 4 accessories. In 1949 (Rewitness bk. 4 pg. 54) W. E. Anderson set 4 new accessories for the section corner. In 1955 (A-612) W.E. Anderson either found or set 3" iron pipe for corner. In 1960 (A-853) M.H. Easton found 3" Iron pipe for the section corner. In 1966 Alan E. Duncan (Rewitness card 206) set a hex bar for the corner inside a found 2.5" Iron Pipe. In 1973 The Tillamook County Surveyors office (Rewitness card # 206) set a 2" Iron pipe with a 3" Tillamook County Brass cap over the top of the 1" hex bar in 10" tile and concrete stamped as shown hereon. In 2021 Tillamook County Surveyors office found the section corner as shown hereon, no accessories to the corner were found.


New accessories set:

Set: 84" hat section post with yellow metal location tag 1.3' North.
Found: P. P. & L. transmission line pole South 32° East 8.4' to face of pole
Found: P. P. & L. transmission line pole South 40° West 12' to face of pole

The Monument was tied directly using G.P.S. established control. The coordinates have been converted and are provided here in WGS 84, Latitude and Longitude.

Latitude: 45° 28' 40"
Longitude: - 123° 49' 25"

Pictures of Found Monuments:



Location: ±1.1 miles East on Latimer Rd. from intersection of Hwy 101, 7' south of edge of pavement, 8' West of center of transmission line.

Tillamook County Surveyor office: 1510 3rd Street Suite C, Tillamook, OR. 97141

Party Chief: Terry Jones, P.L.S. 2507, Survey Supervisor

Witnesses: Michael Rice, P.L.S. 86926, Tillamook County Surveyor
Travis Porter, Survey Tech.

Notes: Digital images taken of monument and accessories.

SURVEYOR'S SEAL

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Terry J. Jones

REGON
JULY 25, 1991
TERRY L. JONES
2507

RENEWAL DATE: JUNE 30, 2023

