

Project Pictures

Meda Loop Road Culvert 1708



Figure 1: Looking towards outlet



Figure 2: Wetland looking upstream from road



Figure 3: Looking downstream from culvert

Irish Road Culvert 1700



Figure 4: Inlet from top of road



Figure 5: Outlet



Figure 6: Substrate upstream from culvert

Trask River Road Culvert 918



Figure 7: Inlet



Figure 8: Outlet



Figure 9: Looking downstream from road

Sandlake Road Culvert SL22



Figure 10: Inlet



Figure 11: Outlet



Figure 12: Stream ditched along road