

C	<p>CHAINS $\frac{1}{4}$ cor bet Sec 10, 11 T3S R10W</p>	<p>Corner is one inch iron pipe in fence line and is approx. 132 ft. south of center line of present road. BT's are; 14" alder (in bark) S67E, 147.2 ft 10" alder (in bark) S20E, 373.0 ft. In the presence of W. E. Anderson and Francis L. Smith, Dec. 7, 1950</p>
C	<p>$\frac{1}{4}$ cor on south line of sec. 32 T3N R9W</p>	<p>Set $1\frac{1}{2}$" iron pipe and remarked original BT which is a 72" cedar stump and bears N70W, 10.9 ft. Made one new BT, 24" spruce tree on south side of road Bearing S18-30E, 49.3 ft. Pipe is in ditch on north side of road. In the presence of W. E. Anderson and Francis L. Smith, Dec. 21, 1950.</p>
Z	<p>SW cor of Hendricks D.L.C.#43 T1S R10W</p>	<p>2" iron pipe wit nob on fence line south of private road. BT's are; 40" spruce N57E, 75.8 ft 24" hem N10W, 61.7 ft. In the presence of Francis L. Smith and W.E. Anderson Dec.27, 1950</p>
J	<p>Sec cor 8,9,16,17 T2S R10W</p>	<p>Rewitness, found old 4X4 spruce limb post scribed and driven into top of $1\frac{1}{2}$" iron pipe. new BT 10" spruce S32E, 96.8 ft. old Bt 48" spruce S15W, 66.0 ft. old BT 70" spruce N64E, 71.9 ft. new BT 48" spruce N13W, 94.0 ft. this is a double tree (48" trunks start spreading at roots). In the presence of W.E. Anderson and Francis L. Smith Dec. 27, 1950.</p>
C	<p>$\frac{1}{4}$ cor bet sec 24,25 T1S R10W Dec 30, 1950</p>	<p>Found a 30" dead spruce stump cut off 10 ft. above ground N21W, 5.9 ft. from cor marks badly burned, remarked same tree. Set $1\frac{1}{2}$" iron pipe $\frac{3}{4}$ ft north of drainage ditch from which a 20" spruce bears S65W, 34.3 ft and a 12" spruce bears S35E, 63.9 ft. The old BT, a 20" spruce, S50E is probably covered over beneath the dike. The farmer who owns the place on the north of sec line showed us the BT which he said had the marks plainly visible in 1934 before the ditch and dike were constructed. In the presence of W.E. Anderson and Francis L. Smith Dec. 30, 1950</p>
C	<p>Sec cor 8,9,16,17 T2S R10W $\frac{1}{4}$ cor bet Sec 13, 14 T1S R10W</p>	<p>Set $1\frac{1}{2}$" iron pipe 4 ft south of private road and approx 35 ft. north of Wilson River from which a tel pole bears N79E, 60.67 ft from which a 12" alder 2 ft north of a 60" rotten stump bears S72-30W, 110.63 ft. In the presence of W.E. Anderson and Francis L. Smith, Dec. 28, 1950.</p>
C	<p>Sec cor 24,25,19, 30 T2N R9-10W</p>	<p>Fir 8" is S42E, 24 links is dead but marks are plainly visible. Fir, 5" N85E 23 links can be identified by the size, position and old face but it is so dead and rotten that no iron marks can be deciphered. Fir 3", S25W 14 links is gone without a trace. From these two original BT'S in Oct. 1949 in the presence of Ray Watkins I set a $\frac{1}{2}$" iron pipe 3 ft long 2 ft in the ground and marked a new BT a live fir 26" in dia. bears S50W, 17.0 ft. S25BT scribed on bark.</p>