**CHAINS** 

## RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 18 and 19, Township 2 North, Range 7 West, W.M., Tillamook County, Oregon.

## ORIGINAL

Stone, now missing, (see 1952 restoration) from which a:

Hemlock bears N6°W 21 lks.; now missing. Hemlock bears S55°E 59 lks.; now missing.

RESTORATION by L. W. Amort, December 17, 1952.

1½th x 36th galvanized iron pipe 10 ft. West of corner point as a witness corner (point now destroyed by roadwork) from which a:

56" Fir snag bears N582°W 83.3 ft.; I destroyed markings.

68th Fir stump bears S30°E 137.0 ft.; I destroyed markings (markings on above BT's destroyed after true corner point was located)

## . RESTORED

Set 1½" x 24" galvanized iron pipe with 3" bronze cap marked "CREGON STATE BOARD OF FORESTRY 1/4 S18 S19 1954 RE 2311,"

20 inches in roadbed on South side. Erected mound of stone around pipe from which a:

52" Fir stump bears S45½°E 144.4 ft.; scribed ½ S19 BT RE 2311.

33" Fir snag bears N86½°E 23.0 ft.; scribed ½ S18 BT.

Oregon State Board of Forestry metal location poster on 33th Fir snag BT.

Also poster on  $52^{tt}$  Fir stump BT.  $4^{tt} \times 5^{tt} \times 80^{tt}$  white Cedar post 1 ft. East of pipe.

Dated March 24, 1954.

Restored by Mul H. Helson under my direction Arnold G. Gibson, Assistant Engineer.

SSTERED PROFESSION 2311

Donish linest OREGON

10, 10, 1944

Present and Alan Ramage

Book I