

169

## OREGON STATE HIGHWAY COMMISSION

INTER-DEPARTMENT CORRESPONDENCE

Subject:

To:

Section Corner I-6-31-36 T. 1.&amp; 2. N. R. 6.&amp;7. W.

All four original B. T.s are now stumps in good condition. A tree was fell on rock and it is gone. Set five foot piece of inch and a quarter pipe, with brass cap, four feet in ground. Cap is stamped T. 2. N. R. 7. W. - T. 1. N. R. 7. W. I-6-31-36. Guard stake, 4" x 4" cedar post.

March 1943

Quarter corner between I-36 T. 1.&amp; 2. N. R. 7. W.

Found original stone with squared stake set by Anderson. Remarkd his 18" fir N. 13° E. 25.5 as scribing was burnt out. His 60" fir N. 67° E. 37.7 was fell just above bottom of blaze; remarked below old blaze 1/4 B.T. Set 54" of inch and a quarter pipe with brass cap. Cap is stamped T. 2. N. R. 7. W. -- T. 1. N. R. 7. W. S. 36 & S.I Guard post--4"x4" cedar post.

March 1943

*Rehalem On  
12/31/43  
The above work done by  
Claude Mahaw, transit man  
ad party, under my direction  
J. S. Scott  
Resident Engineer*

Book I

169

169