

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter section corner common to Sections 5 and 32,
T. 3 & 4 N., R. 6W., W.M., Clatsop & Tillamook Counties, Oregon

ORIGINAL

20" Hemlock for corner, now in place and rotted, from
which a:

- 36" Fir bears North 9 lks.; now burnt out stub 10' high.
- 24" Hemlock bears S75°E 54 lks.; now 28" rotted stub,
portion of scribes $\frac{1}{4}$ BT visible.

RESTORATION by State Highway Department

Left original $\frac{1}{4}$ corner tree in place from which a:

2" galvanized iron pipe bears East 40" mkd. " $\frac{1}{4}$ cor. W.C.
Tps. 3 & 4 N, R6W."

RESTORED

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S32 S5 1955 RE 2311,"
33 inches in ground, in mound of stone, and from which a:

33" Cedar stump bears S61°E 59.3 ft.; scribed $\frac{1}{4}$ S 5 BT
RE 2311.

24" Fir stump bears N53 $\frac{1}{2}$ °W 100.2 ft.; scribed $\frac{1}{4}$ S32 BT

Set 4"x4"x72" white Cedar post N80°W 30" from O.S.B.F. pipe.
Oregon State Board of Forestry metal location poster on 33"
Cedar stump BT.

Oregon State Board of Forestry metal location poster on
4"x4"x72" white Cedar post 255' S on N edge logging Rd.
General Land Office poster on original 28" Hem. stub BT.

March 11, 1955

Restored by Arnold G. Gibson under my direction.
Arnold G. Gibson, Asst. Engr.



Present and witnessed by Claude Weikel
Lloyd Geraths