

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter corner for Section 36 (South boundary), T1N, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Post (missing) from which a:

16" Hemlock bears N11E 50 lks.; (now bears N11W) badly burned face and portion of scribe visible.

20" Hemlock bears S31W 72 lks.; now 31" stump, part of face remaining with all scribes burnt away.

RESTORED 1884

Set basalt stone 12" x 9" x 6" (now missing)

RESTORED

Var. 21 1/2 E


Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S36 1959 RS401", 34 inches in ground, in mound of stone, and from which a:

49" Fir stump bears N65W 13.1 ft.; scribed 1/4 S36 BT RS401.


Oregon State Board of Forestry metal location poster on 49" Fir stump BT. Set 4" x 4" x 48" white painted Cedar post 1.5' N.W. of pipe.

Dated August 4, 1959

Restored by Harold J. Russell under my direction.  
Harold Russell, Eng. Tech. I



*Richard A. Morris*



Present and witnessed by R. Cop  
E. Nylund  
D. Jones