

## BAYSIDE SURVEYING

11765 HWY 101 South  
Tillamook, Oregon 97141

Terry L. Jones  
503-842-5551  
Fax 503-842-5552

April 2002

### REWITNESS

¼ CORNER COMMON TO SECTIONS 22 and 27  
TOWNSHIP 2 SOUTH, RANGE 8 WEST

I Found:

OSBF brass cap stamped "¼ S22 S27 1966 RS 707" in stone mound, on steep East slope, approximately 50' East of road. (See MAP B-531)

From which:

72" Fir stump, rotten, with location tag, bears N80½°E 17.6'. (72" Fir stump N80½°E 17.6'. See MAP B-531)

NE BT gone. (67" Fir stump N51¾°E 78.0'. See MAP B-531)

Location tag on a 13" Alder on east side of road N78½°W 650' (YMLP on 5" Alder on E. edge road N78½°W approx. 50'. See MAP B-531)

---

I set:

An Orange carsonite post 4' North, and 2 New BTs as follows:

16" Douglas Fir scribed "1/4 S27 BT" bears S61°E 45.1' to brass nail & washer stamped "LS 2507" between the B & T;

13" Alder bark scribed "1/4 S22 BT" bears N15°E 15.4' to brass nail & washer stamped "LS 2507" between the B & T;

In the presence of Terry Jones, Dallas Esplin

