


**OREGON PUBLIC LAND CORNER REPORT/RESTORATION REPORT**  
**Tillamook County Surveyor's Office**

<b>SECTION:</b> 19	<b>TOWNSHIP:</b> 3 South	<b>RANGE:</b> 9 West
<b>COUNTY:</b> Tillamook		<b>DATE:</b> 9/5/2007
<b>CORNER DESIGNATION:</b> West 1/16 corner on the North line of Sec.19		<b>(Please Check One)</b>
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Not Found
		<input type="checkbox"/> Reset
		<input type="checkbox"/> Referenced Out
<b>Previous Rewitnesses, Restorations, Surveys, etc.:</b> Map B-830		
<b>Found Monument(s) and Accessories(Condition &amp; Source):</b> Found USFS aluminum cap with steel post with white sign 1.2 feet West (both bearing trees are on the ground and rotten).		
<b>Monument Set(Procedures &amp; Description):</b> Monument in good condition		T3S      R9W  S18 W 1/16      S19  1979 PLS 896
<b>Other New Accessories Set:</b> Set second Steel Post 81 Feet South Also attached yellow "GREEN DIAMOND" property line tags on the post, painted top red and hung orange flagging.		
<b>New Bearing Trees:</b> Marked 2 new bearing trees as indicated 6" hemlock scribed "T3SR9WS19B T" on low face with brass nail and washer marked "LS 2507" between the B & T bears South 13 West 23.44 feet.      8" hemlock scribed "T3SR9WS18B T" on low face with brass nail and washer marked "LS 2507" between the B & T bears North 58 East 9.84 feet.		
		<b>Surveyor's Stamp</b>
<b>Firm/Agency:</b> Bayside Surveying		
<b>Address:</b> 11765 Hwy. 101 South Tillamook, OR 97141		renewal date 6-30-09
<b>Party Chief:</b> Terry L. Jones		Office Use Only
<b>Notes:</b> in 3S 9 19 file in office		
<b>Witness(es):</b> Dallis Esplin Anthony Wright		