

**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
Tillamook County Surveyor's Office

<b>SECTION: SE Corner 21</b>	<b>TOWNSHIP 1 South</b>	<b>RANGE 10 West</b>	
<b>COUNTY: Tillamook</b>		<b>DATE: 2-13-09</b>	
<b>CORNER DESIGNATION:</b> The Section Corner Common to Sections 21, 22, 27 and 28, T. 1 S., R. 10 W., W.M.		<b>(Please check one)</b>	
		<input type="checkbox"/>	Condition Report Only
		<input type="checkbox"/>	Restoration
		<input checked="" type="checkbox"/>	Rewitness
		<input type="checkbox"/>	Unrecorded
		<input type="checkbox"/>	Reset at surface
		<input type="checkbox"/>	Referenced Out
<b>Previous Rewitnesses, Restorations and Surveys, etc:</b> BLM Field Notes Volume: OR-R0053 Page 197 (GLO 1S10 Pg. 32) (1857), Map B-1302 (1988), Book 6 Page 349 (1988), Rewitness #311 (1988), Tillamook County Survey Records.			
<b>Found Monument(s) and Accessories (Condition &amp; Source):</b> Found a 2 1/2" brass cap in cement, up 1.0'. The monument is stamped as shown hereon. Tied the monument conventionally using GPS established control. The Oregon North Zone State Plane in NAD 83/91 coordinate for the monument is N = 673502.156, E = 7328355.1538. Found a hat section post with a yellow metal location tag S 50° E 1.5' from monument. Found a white cedar post West 1.5' from the monument. (G.L.O.) – Found 36" (was 24") Hemlock snag, 10' tall, chopped out face with nail, bears (S31° E) 36.9' (36.3'). ( ) Indicates G.L.O. record information, Tillamook County Survey Records.			
<b>Monument Set (Procedures and Description):</b> Not applicable.		<b>Sketch of Found Monument:</b>	
<b>New accessories set:</b> Rotated the monument north and set a rock collar. Set 120 lbs. of concrete over rock collar. Set a 5/8" X 30" Iron rod with a red plastic cap marked, "Tillamook Co. Survey" on the east edge of logging road #704 as an occupy point to tie the monument conventionally. The Oregon North Zone State Plane NAD 83/91 coordinate for said point is N = 673482.0570, E = 7328310.7180. Set a 5/8" X 30" Iron rod with a red plastic cap marked, "Tillamook Co. Survey" on the east edge of logging road #704 as a backsight point to tie the monument conventionally. The Oregon North Zone State Plane NAD 83/91 coordinate for said point is N = 673191.4770, E = 7328313.2940.			
<b>New Bearing Trees set:</b> 16" diameter Hemlock bears N 70° W 83.3', scribed, "T1S R10W S21 BT", tagged and painted. 13" diameter Hemlock bears N 48° E 21.5', scribed, "T1S R10W S22 BT", tagged and painted. 13" diameter Hemlock bears S 34° E 53.9', scribed, "T1S R10W S27 BT", tagged and painted. 14" diameter Hemlock bears S 48° W 105.0', scribed, "T1S R10W S28 BT", tagged and painted. All new bearing trees have a nail and aluminum washer marked, "Till. Co. Surveyor", in face of blaze, between the scribed B and T, and a yellow metal location tag affixed.			
<b>Location &amp; Comments:</b> Corner is located approx. 50' east of a logging road #704.			
<b>Firm / Agency</b> Address: <b>TILLAMOOK COUNTY SURVEYOR'S OFFICE</b> 201 Laurel Avenue Tillamook, Oregon 97141		<b>SURVEYOR'S SEAL</b>	
<b>Party Chief:</b> Joe Jensen, P.L.S. 60067, Survey Supervisor			
<b>Notes:</b>			
<b>Witnesses:</b> Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician			