

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: North 1/4 corner of Section 5	TOWNSHIP: 2 South	RANGE: 9 West
COUNTY: Tillamook		DATE: 08-29-09
The North 1/4 corner of Section 5, Township 2 South, Range 9 West, W.M., Tillamook County, Oregon.		(Please check one)
		<input type="checkbox"/> Condition Report Only
		<input type="checkbox"/> Restoration
		<input checked="" type="checkbox"/> Rewitness
		<input type="checkbox"/> Unrecorded
		<input checked="" type="checkbox"/> Brass Cap set at surface
<input checked="" type="checkbox"/> Referenced Out		
Previous Rewitnesses, Restorations and Surveys, etc: Rewitness Card #360; Survey maps A-2343, A-3961, A-4496, B-75, B-178, B-612, B-1400, F-40-87, Fieldbook CL 9, Page 22, Book S3, Page 492, Tillamook County Survey Records.		
Found Monument(s) and Accessories (Condition & Source): The 3" diameter brass cap as described on Rewitness Card #360 was destroyed due to an asphalt grinding project. Found the hat section post at record position (South 19.5'). The two power poles that were set as new accessories on Rewitness Card #360 are now gone.		
() – Indicates record value from Rewitness card #360		
Monument Set (Procedures and Description): Set a 2" diameter brass cap in concrete at the road surface. The monument is stamped as shown hereon.		Sketch of Monument Set at Surface:
New accessories set: Prior to the destruction of the 3" diameter brass cap, two reference monuments were set as points on line to the monument. A 5/8" rebar with red plastic cap stamped "TILLAMOOK CO SURVEY" which bears South 14° East (compass bearing) a distance of 20.51'. This reference monument is located in an existing driveway, approximately 3.0' East of an existing sawed off power pole now used as a fence post. Also a 5/8" rebar with red plastic cap stamped "TILLAMOOK CO SURVEY" which bears North 14° West (compass bearing) a distance of 24.66' and is located 5.0' North of an East-West fence line.		
New Bearing Trees set: No new bearing trees were set.		
Location & Comments: This corner is located in the center of the asphalt pavement of McCormick Loop Road (aka Mapes County Road).		
Firm / Agency Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141		SURVEYOR'S SEAL
Party Chief: Joe Jensen, PLS 60067, Survey Supervisor		
Notes: Digital images were taken of the set surface monument.		
Witnesses: Danny R. McNutt, PLS 49230, Tillamook County Surveyor. Michael R. Rice, L.S.I. 16723, Survey Technician		

