

**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
**Tillamook County Surveyor's Office**

<b>SECTION: The South 1/4 Corner of Section 30</b>	<b>TOWNSHIP 2 South</b>	<b>RANGE 9 West</b>
--	-------------------------	---------------------

<b>COUNTY: Tillamook</b>	<b>DATE: 08-25-10</b>
--------------------------	-----------------------

<b>CORNER DESIGNATION:</b> The quarter corner common to Sections 30 and 31, Township 2 South, Range 9 West, W.M., Tillamook County, Oregon.	<table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th align="center" colspan="2">(Please check one)</th> </tr> <tr> <td><input type="checkbox"/></td> <td>Condition Report Only</td> </tr> <tr> <td><input type="checkbox"/></td> <td>Restoration</td> </tr> <tr> <td><input checked="" type="checkbox"/></td> <td>Rewitness</td> </tr> <tr> <td><input type="checkbox"/></td> <td>Unrecorded</td> </tr> <tr> <td><input type="checkbox"/></td> <td>Reset at surface</td> </tr> <tr> <td><input type="checkbox"/></td> <td>Referenced Out</td> </tr> </table>	(Please check one)		<input type="checkbox"/>	Condition Report Only	<input type="checkbox"/>	Restoration	<input checked="" type="checkbox"/>	Rewitness	<input type="checkbox"/>	Unrecorded	<input type="checkbox"/>	Reset at surface	<input type="checkbox"/>	Referenced Out
(Please check one)															
<input type="checkbox"/>	Condition Report Only														
<input type="checkbox"/>	Restoration														
<input checked="" type="checkbox"/>	Rewitness														
<input type="checkbox"/>	Unrecorded														
<input type="checkbox"/>	Reset at surface														
<input type="checkbox"/>	Referenced Out														

**Previous Rewitnesses, Restorations and Surveys, etc.:** BLM Field Notes Volume: OR-R0053 Page 361; Tillamook County GLO Book 2S09, Pg. 19 (1857); Tillamook County Field Note 1910 P17, Page 37; Rewitness Book 4, Page 45; Rewitness Book 4, Page 42; Map A-4455, B-184, B-1137, B-1231, B-2083, F-40-35, Tillamook County Survey Records.

**Found Monument(s) and Accessories (Condition & Source):** Found a 1-1/2" diameter aluminum cap on a 5/8" iron rod flush with the ground and in good condition. This monument was set by C. Wayne Cook, P.L.S. 1098 on map A-4455 done in 1981. Found a very rotten Hemlock stump, approximately 8" in diameter, at record position, with a yellow metal location tag found on the underside of the rotten stump; (was a 6" diameter Hemlock tree bearing N66° W 22.2' scribed "1/4 S30BTRS1098"). Found a 38" diameter Hemlock tree with a healed face and yellow metal location tag at record position (was a 30" diameter Hemlock tree bearing S69° E 12.3' scribed "1/4 S31BT").

<p><b>Sketch of Monument Set (Procedures and Description):</b> Placed a 3" Tillamook County Brass cap on a 1 1/2" diameter galvanized iron pipe over the found 5/8" x 1-1/2" aluminum cap. Placed a 12" diameter plastic cylinder and 120 pounds of concrete around the set monument. Set a 72" hat section post 2.0' South of monument.</p> <div style="text-align: center;"> </div>	<p><b>Sketch of Found Monument:</b></p> <div style="text-align: center;"> </div>
---	--

**New accessories set:** See section above.

**New Bearing Trees Set :**  
 61" diameter Douglas Fir stump, 10' tall with chopped face with nail and aluminum washer which bears South 58° West 12.9'.  
 10" diameter Hemlock tree scribed "T2SR9W1/4S30BT" which bears North 15° East 36.5'.  
 11" diameter Hemlock tree scribed "T2SR9W1/4S30BT" which bears North 44° East 30.1'.

All new bearing trees have a nail and aluminum washer marked, "Till. Co. Surveyor", in face of blaze, between the scribed B and T, and a yellow metal location tag affixed.

**Location & Comments:** This corner is located approximately 100 feet West of a spur logging road coming off of S25 Road.

<b>Firm / Agency</b> <b>Address:</b> TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141
<b>Party Chief:</b> Joe Jensen, PLS 60067, Survey Supervisor
<b>Notes:</b> Digital images were taken of the monument and the new accessories.
<b>Witness:</b> Danny R. McNutt, PLS 49230, Tillamook County Surveyor; Michael R. Rice, L.S.I. 16723, Survey Technician

**SURVEYOR'S SEAL**

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Joseph V. Jensen*

OREGON  
JANUARY 10, 2008  
JOSEPH V. JENSEN  
60067

RENEWAL DATE: 08-30-

