

**OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT**  
Tillamook County Surveyor's Office

<b>SECTION:</b> 10, 15	<b>TOWNSHIP</b> 1 North	<b>RANGE</b> 10 West
------------------------	-------------------------	----------------------

<b>COUNTY:</b> Tillamook	<b>DATE:</b> 8-17-10
--------------------------	----------------------

<b>CORNER DESIGNATION:</b> The Quarter Corner common to Sections 10 and 15, T. 1 N., R. 10 W., W.M.	<b>(Please check one)</b>	
	<input type="checkbox"/>	Condition Report Only
	<input type="checkbox"/>	Restoration
	<input checked="" type="checkbox"/>	Rewitness
	<input type="checkbox"/>	Unrecorded
	<input type="checkbox"/>	Reset at surface
<input type="checkbox"/>		Referenced Out

**Previous Rewitnesses, Restorations and Surveys, etc:** BLM Field Notes Volume: OR-R0122 Page 78, (GLO Book 1N10 Page 43) (1873), Map B-437 (1959), Rewitness Book 2 Page 446 (1960), Map A-1206 (1964), Rewitness Book 7 Page 80 (1991), Tillamook County Survey Records.

**Found Monument(s) and Accessories (Condition & Source):** Found a 3" diameter Oregon State Board of Forestry Brass Cap in good condition, in concrete, up 0.4', as restored in Book 2, Page 446. The monument is stamped as shown hereon. Found a white painted cedar post lying next to the monument. Found a hat section post with a yellow metal location tag North 1.6' from monument as set in Book 7, Page 80.  
 (G.L.O.) – Did not find the (40" Hemlock bears S 20° E 17 lks. [11.22']).  
 (G.L.O.) – Did not find the (36" Hemlock bears N 10° W 30 lks. [19.8']).  
 (Book 2, Page 446) – Found 5" Hemlock Stub (was 12"), 3' tall, badly rotten, (bears N 55 1/2° E 16.0'), no marks visible.  
 (Book 2, Page 446) – Found 21" Hemlock Stump (was 16"), 5' tall, badly rotten, (bears S 30 1/2° E 14.4'), face overgrown.  
 ( ) Indicates record information, Tillamook County Survey Records.  
 [ ] Indicates converted value from links to feet.

<b>Monument Set (Procedures and Description):</b> N/A	<b>Sketch of Found Monument:</b>

**New accessories:** N/A

**New Bearing Trees:**  
 \* 14" diameter D. Fir bears N 41° E 14.6', scribed "T1NR10WS10BT", flagged and painted.  
 \* 14" diameter Hemlock bears S 37° E 7.0', scribed "T1NR10W1/4S15BT", flagged and painted.  
 \* 10" diameter D. Fir bears S 59° W 5.8', scribed "T1NR10WS15BT", flagged and painted.  
 \* 15" diameter D. Fir bears N 74° W 19.5', scribed "T1NR10W1/4S10BT", flagged and painted.  
 \* Indicates aluminum nail with a washer stamped "Till. Co. Surveyor" in face of tree between the scribed "B" and "T" and a yellow metal location tag affixed.

**Location & Comments:** This corner is located approximately 50' west of a gravel logging road.

<b>Firm / Agency</b> Address: TILLAMOOK COUNTY SURVEYOR'S OFFICE 201 Laurel Avenue Tillamook, Oregon 97141
<b>Party Chief:</b> Joe Jensen, P.L.S. 60067, Survey Supervisor
<b>Notes:</b> Digital images were taken of the monument and the accessories.
<b>Witnesses:</b> Danny R. McNutt, P.L.S. 49230, Tillamook County Surveyor Michael R. Rice, L.S.I. 16723, Survey Technician

**SURVEYOR'S SEAL**

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**

*Joseph V. Jensen*

**OREGON  
JANUARY 10, 2008  
JOSEPH V. JENSEN  
60067**

RENEWAL DATE: 06-30-2011

