



OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 31, 32, 6, 5	TOWNSHIP: 1S & 2S	RANGE: 9W
-----------------------	-------------------	-----------

COUNTY: Tillamook	DATE: 6/8/2017
-------------------	----------------

CORNER DESIGNATION: Section Corner of T1S R9W Sec 31 & 32 and T2S 9W Sec 6 & 5	(Please check one)		
	<input type="checkbox"/>	Condition Report Only	
	<input type="checkbox"/>	Restoration	
	<input checked="" type="checkbox"/>	Rewitness	
	<input type="checkbox"/>	Unrecorded	
	<input type="checkbox"/>	Reset at surface	
		<input type="checkbox"/>	Referenced Out

Previous Rewitnesses, Restorations and Surveys, etc.. GLO 1 & 2 South pg. 48 (1893), Rewitness Book 4 pg. 19 (1905), Rewitness Book 3 pg. 59 (1946), Rewitness Book 5 pg. 150 (1965), Rewitness Card #361 (1974), A-0194 (1815), A-0408 (1950), A-1446 (1967), A-1447 (1967), A-5369 (1968), A-1699 (1969), A-2040 (1970), A-3558 (1978), B-0075 (1921), B-1216 (1986), B-1400 (1989), Tillamook County Records.

Found Monument(s) and Accessories (Condition & Source): The Section corner was first set in September of 1893 by Henry Meldrum. He set a wooden post and four bearing trees. In 1905 Joseph Saudero set a 4" Sharpened Spruce limb and one new accessory. In May 1946 J.H. Scott set a 3' x 1 1/4" galvanized pipe with a white post. In November of 1965 Tillamook County Surveyors office set 2 new accessories. In 1974 the Tillamook County Surveyors office set a 2" iron pipe with a 3" brass cap set in concrete at location and added a hat section post.

(Rewitness Book 5 pg. 150 1965)- Power Pole #11 with scribing N49°W 80.92'; now gone
 (Rewitness Book 5 pg. 150 1965)- S.W corner of barn N14°E 103.48'; Found; now N 9°40'52" E 103.23'
 Spruce limb alongside Iron rod; Not Found
 (Rewitness Card #361 1974)- Hat Section Marker with Location tag East 2.6'; Found now East 1.3'

Monument Set (Procedures and Description):



New accessories set: Coordinates given are only for locating monument.
 The Found Monument was conventionally tied using GPS control. WGS 84: Latitude: N45°26'03" Longitude: W123°49'27"
 Found: Power Pole #318104 N 54°43'49" W 69.20'
 Found: Iron Rod with Yellow plastic cap S 1°00'46" E 176.42'

New Bearing Trees set:

Location & Comments: The monument is located ±2 miles South of Tillamook ±96' East of edge of pavement of Hwy 101 and ± 57' South of McCormick Loop Road.

Firm / Agency Tillamook County Surveyors Office
Address: 1510 3rd Street Suite C Tillamook, OR. 97141.

Party Chief: Joe Jensen, P.L.S. 60067, Survey Supervisor

Notes: Digital images taken of monument and accessories.

Witnesses: Michael Rice, P.L.S. 86926, Tillamook County Surveyor
 Travis Porter, Survey Tech.

SURVEYOR'S SEAL

**REGISTERED
PROFESSIONAL
LAND SURVEYOR**

Joseph V. Jensen

**OREGON
JANUARY 10, 2008
JOSEPH V. JENSEN
60067**

RENEWAL DATE: 06-30-19