



OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT  
Tillamook County Surveyor's Office

<b>SECTION:</b> Section 36 Section 31	<b>TOWNSHIP</b> 5 South TOWNSHIP 5 South	<b>RANGE</b> 11 West RANGE 10 West
--	---	---------------------------------------

<b>COUNTY:</b> Tillamook	<b>DATE:</b> 07-27-15
--------------------------	-----------------------

<b>CORNER DESIGNATION:</b> Section corner common to Section 36, T5S, R11W; Section 31, T5S, R10W; W.M.,	<b>(Please check one)</b>	
	<input type="checkbox"/>	Condition Report Only
	<input checked="" type="checkbox"/>	Restoration
	<input type="checkbox"/>	Rewitness
	<input type="checkbox"/>	Unrecorded
	<input checked="" type="checkbox"/>	Reset at surface
	<input type="checkbox"/>	Referenced Out

**Previous Rewitnesses, Restorations and Surveys, etc:** See BLM Field Note Volume: OR-R0112, Page: 0023; See BLM Field Note Volume: OR-R0338, Page: 0133-135; See BLM Field Note Volume: OR-R0576, Page: 276; See maps B-59, B-1655, B-1684, B-634, B-1278, Tillamook County Survey Records; See Rewitness Book 5, Page 229, Rewitness Book 4, Page 74, Tillamook County Corner Rewitness Records; See Book S3, Page 208; A.M. Austin Field book 2, Page 106; U.G. Jackson Field book 15, Page 52, Tillamook County Field Note Records.

**Found Monument(s) and Accessories (Condition & Source):** Found a 3-1/4" BLM brass cap stamped "SC T5S R11W R10W S36 S31 1962" under asphalt pavement of Slab Creek County Road. Set a 2" diameter brass cap stamped "Tillamook County Surveyor" in concrete and at road surface. The 2" diameter brass cap is stamped as shown hereon. **Found:** a 3-1/4" BLM brass cap stamped "T5S R10W S31 SC RM 1962" which bears N48°20'39"E 52.02' (BLM OR-R0576 Page 276 N48°16'E 79 lks.), (B-1684 = N48°16'E 52.2'), (B-1278 = N48°14'27"E 52.31'); Found a 2-1/2" brass cap stamped "T5S R11W S36 S1 S6 R11W R10W T6S 1973 RPLS 942 in concrete cylinder which bears S89°44'53"W 89.12' (B-1684 = S89°44'53"W 89.14'), (B-1644 = S89°44'34"W 89.11'), (BLM OR-R0576 Page 276 = S89°34'W 1.345 chs.); a 2-1/2" BLM brass cap stamped "T5S R11W S36 SC RM 1962" at record position, (BLM OR-R0576 Page 276 = N41°10'W 79 lks.), (B-1684 = N41°48'E 52.7');

**Monument Set (Procedures and Description):** Set a 2" diameter brass cap stamped "T5S R11W R10W S36 S31 2015" in concrete at road surface. We referenced the found 3-1/4" BLM brass cap by setting rock nails in the existing asphalt pavement.

Grid coordinate horizontal datum information for the 2" diameter brass cap: Oregon North Zone, State Plane Coordinates, NAD '83-'91, U.S. Survey Foot: Northing = 537287.916, Easting = 7307152.622.  
WGS84 = Latitude 45°05'15.92129"; Longitude 123°57'58.60517".

Picture of Set Monument:



**Reference monuments set:** Set a 5/8" x 6" rebar with a yellow plastic cap stamped "Tillamook Co. Random" in the West shoulder of Slab Creek County Road which bears N12°26'18"W 128.58';

**New Bearing Trees set:** No new bearing trees set.

**Location & Comments:** The corner is located approximately one foot east of the centerline of Slab Creek Road.

**Firm / Agency:**  
**Address:** TILLAMOOK COUNTY SURVEYOR'S OFFICE  
1510 Third Street, Suite C  
Tillamook, Oregon 97141

**Party Chief:** Danny R. McNutt P.L.S. 49230, Tillamook County Surveyor.

**Notes:** Digital images were taken of the set monument.

**Witnesses:** Joe Jensen, P.L.S. 60067, Survey Supervisor  
Mike Rice, Survey Technician.

**SURVEYOR'S SEAL**

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Joseph V. Jensen*

OREGON  
JANUARY 10, 2008  
JOSEPH V. JENSEN  
60067

RENEWAL DATE: 06-30-17