

OREGON PUBLIC LAND CORNER REPORT / RESTORATION REPORT
Tillamook County Surveyor's Office

SECTION: 36	TOWNSHIP: 5 S	RANGE: 10 W
COUNTY: Tillamook		DATE: 11-1-18
CORNER DESIGNATION: SOUTHWEST 1/16 CORNER Section 36		(Please check one)
		Condition Report Only
		Restoration
		Rewitness
		Unrecorded
		Reset at surface
		<input checked="" type="checkbox"/> Referenced Out

Previous Rewitnesses, Restorations and Surveys, etc: Survey B-1107, A-2512
REWITNESS BOOK 5, PAGE 261, 266 (1972) TILLAMOOK COUNTY SURVEY RECORDS

Found Monument(s) and Accessories (Condition & Source): Found USFS 3-1/4" Aluminum Cap on pipe 4" above surface, with carsonite posts North and South about 5 ft. on Westerly slope. Per B-1107

14" Hemlock remains only N 20°E 37.6 feet, no marks remaining, Per B-1107
24" Hemlock stump remains only S 06°E 19.5 ft, no marks remaining, per B-1107
BT's per B-1107 not found: 18" Hemlock S 88°W 27.5'
32" Hemlock NE 34.4'

Monument Set (Procedures and Description):
none

Pictures of Found Monuments:

USDA FOREST SERVICE
T5S R10W
SW 1/16 - S36
1983
PLS 981
DO NOT DISTURB

New accessories set:

New Bearing Trees set: 11" Hemlock N 05°E 23.3 ft. scribed "SW1/16S36" above "BT".
20" Hemlock S 78°E 20.6 ft. scribed "SW1/16S36" above "BT".

Location & Comments: pipe up 4"
With carsonite posts North and South about 5 ft. on Westerly slope.

Firm / Agency NORTHSTAR SURVEYING 720 NW 4TH ST.
CORVALLIS, OREGON 97330 - 541-757-9050
Address:
Party Chief: MARK GANDY
Notes:
Witnesses: JOHNNY RODERICK

SURVEYOR'S SEAL

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
JULY 26, 1985
ROBERT A. COOK
2338

RENEWS 12-31-2019

