

4 Contd.

County Surveyor's Record, Tillamook County, Oregon

T4SR9W

Rewitnessed corners Leonard Whitmore, U.S. Forest Service, Hebo

$\frac{1}{4}$  cor. Original post still standing mkd. S16 on N. side with a rock mound at its base.

$\frac{16}{21}$  48 in. fir, N. 48°30' E., 185½ ft. (original BT)  
16 in. fir, S.63°30' W., 46½ ft mkd.  $\frac{1}{4}$ S21BT (new BT)

In the presence of Mervin Whitmore, February 22, 1961

Sec. Cor.

$\frac{15}{22}$   $\frac{14}{23}$  Original stone alongside  $\frac{1}{2}$  in. pipe 2 ft. above ground  
10 in. fir, S.40°E., 1½ ft. mkd. T4SR9WS23BT (new BT)  
14 in. fir, S.16°W., 10½ ft. mkd. T4SR9WS22BT (new BT)  
16 in. Fir, N.22°W., 20 ft. mkd. T4SR9WS15BT (new BT)  
8 in. fir, N55°30'E., 15 ft. mkd. T4SR9WS14BT (new BT)

In the presence of Mervin Whitmore, Sept. 3, 1960

John Lundgren  
Daryl Whitmore

$\frac{1}{4}$  cor.

$\frac{14}{23}$   $\frac{1}{2}$  in. pipe alongside original post  
20 in. Hemlock, S.33°W., 9 ft. mkd.  $\frac{1}{4}$ S23BT (New BT)  
12 in. fir, N.50°W. 22½ ft. mkd.  $\frac{1}{4}$ S14BT (new BT)

Corner is approx.  $\frac{1}{4}$  mile east of Mt. Hebo Airbase.

In the presence of Mervin Whitmore, Dec. 25, 1960  
Daryl Whitmore

$\frac{1}{4}$  cor.

$\frac{15}{14}$   $\frac{1}{2}$  in. pipe alongside original post with a mound of stone at the east base.  
44 in. fir, S.58°W., 36 ft. mkd.  $\frac{1}{4}$ S15BT (new BT)  
18 in. fir, S.51°E., 22½ ft mkd.  $\frac{1}{4}$ S14BT (new BT)

In the presence of Mervin Whitmore, Dec. 25, 1960  
Daryl Whitmore

Sec. Cor.

$\frac{11}{14}$   $\frac{12}{13}$  Original post with rock mound at base  
36 in. fir, S.61°15'E., 95 ft. mkd. T4SR9WS13BT (new BT)  
12 in. fir, N.32°30'E., 29 ft. mkd. T4SR9WS12BT (new BT)  
12 in. fir, N.71°W., 46 ft. mkd. T4SR9WS11BT (new BT)  
12 in. fir, S.85°30'W., 26 ft. mkd. T4SR9WS14BT (new BT)

In the presence of Mervin Whitmore, Jan. 28, 1961  
Derrill Derrick

pg-4 of 5  
M Whitmore