

TILLAMOOK COUNTY SURVEYORS OFFICE  
COURTHOUSE, TILLAMOOK, OREGON 97141

SECTION CORNER COMMON SECTIONS 33 & 34 T.1S.; R.10W., W. M.  
& SECTIONS 3 & 4 T.2S., R.10W., W. M.

T1SR10W  
S33 | S34  
+  
S 4 | S 3  
T2SR10W  
1977

I FOUND A 2" IRON PIPE WITH A 3" TILLAMOOK COUNTY SURVEYORS  
BRASS CAP DISTURBED BY LOGGING OPERATION. I RESET FOUND  
MONUMENT FROM EXISTING BEARING TREES AND ENCASED IN AN  
IRREGULAR MASS OF CONCRETE.

---

HISTORY OF FOUND MONUMENT

I FOUND THIS MONUMENT TO BE AS DESCRIBED IN T.C.S. REWITNESS CARD #335 AND THE  
REFERENCES FOUND AND/OR SET AT THAT TIME TO NOW BE AS FOLLOWS:

(G.L.O.) 20" HEMLOCK N.50°E. 15 LINKS; REPORTED IN BOOK 5 AT PAGE 60 AS A 20" HEMLOCK SNAG  
N.50°E. 9.90', SCRIBING VISIBLE. REPORTED ON MAP B-659 AS A 20" HEMLOCK SNAG N.50°E.  
10.9'. AND REPORTED ON REWITNESS CARD #335 AS FOUND ROTTEN STUMP. (FOUND, NOW ROTTED  
STUMP, AT POSITION REPORTED ON MAP B-659).

(G.L.O.) 48" SPRUCE N.18°W. 21 LINKS; REPORTED IN BOOK 5 AT PAGE 60 AS A 48" SPRUCE SNAG  
N.18°W. 19.30' SCRIBING VISIBLE. REPORTED ON MAP B-659 AS A 48" SPRUCE SNAG N.18°W. 19.5'  
SCRIBING VISIBLE. AND REPORTED ON REWITNESS CARD #335 AS FOUND ROTTEN STUMP, SCRIBING  
VISIBLE. (NOW ROTTEN STUMP REMAINS, AT POSITION REPORTED ON MAP B-659).

(G.L.O.) 32" HEMLOCK S.80°W. 31 LINKS; REPORTED IN BOOK 5 AT PAGE 60 AS A 32" HEMLOCK SNAG  
S.80°W. 20.46' NO VISIBLE SCRIBING. REPORTED ON MAP B-659 AS A 32" HEMLOCK SNAG S.44°W.  
19.7'. AND REPORTED ON REWITNESS CARD #335 AS NOT FOUND. (NOW, NOTHING FOUND AT ORIGINAL  
S.80°W. POSITION, BUT FOUND ROTTED STUMP REMAINS AT POSITION REPORTED BY MAP B-659).

(G.L.O.) 56" HEMLOCK S.45°E 19 LINKS; REPORTED IN BOOK 5 AT PAGE 60 AS GONE. AND REPORTED  
ON REWITNESS CARD #335 AS NOT FOUND. (NOW GONE).

(BOOK 4 PAGE 75) 18" HEMLOCK N.80°W. 11.2'; REPORTED IN BOOK 5 AT PAGE 60 AS A 30" HEMLOCK  
N.80°W. 11.2' SCRIBING VISIBLE. REPORTED ON MAP B-659 AS A HEMLOCK N.80°W. 11.2', SCAR  
VISIBLE; AND REPORTED ON REWITNESS CARD #335 AS A 40" HEMLOCK N.80°W. 11.2'; (FOUND; NOW  
40" HEMLOCK STUMP 8' TALL, FACE HEALED OVER, AT POSITION).

(BOOK 4 PAGE 75) 6" HEMLOCK N.80°E. 34.7'; REPORTED IN BOOK 5 AT PAGE 60 AS A 14" HEMLOCK  
N.80°E. 34.70' SCRIBING VISIBLE. REPORTED ON MAP B-659 AS A HEMLOCK N.80°E. SCAR VISIBLE.  
AND REPORTED ON REWITNESS CARD #335 AS A 20" HEMLOCK N.80°W. 34.7'; (FOUND; NOW 28"  
HEMLOCK STUMP 2' TALL, FACE HEALED OVER, AT POSITION).

(BOOK 4 PAGE 75) 6" HEMLOCK N.5°E. 28.6'; REPORTED IN BOOK 5 AT PAGE 60 AS A 10" HEMLOCK  
N.5°E. 28.60', SCRIBING VISIBLE. REPORTED ON MAP B-659 AS A HEMLOCK N.5°E., SCRIBING  
VISIBLE. AND REPORTED ON REWITNESS CARD #335 AS AN 8" HEMLOCK N.5°E. 28.6'; (NOW GONE,  
ROOT HOLE AT POSITION).

(MAP B-659) 22" HEMLOCK S.11°E 35.1'. (FOUND, NOW 28" HEMLOCK STUMP 7' TALL, S.11°E.  
35.1', FACE HEALED OVER).

(REWITNESS CARD #335) FOUND UNRECORDED 18" SPRUCE N.77°W. 22.41'; (FOUND, NOW A 20" STUMP  
7' TALL, AT POSITION BLAZE SAWED OPEN).

(REWITNESS CARD #335) FOUND 24" SPRUCE N.3°E. 35.24', SCRIBING VISIBLE. (NOW GONE).

(REWITNESS CARD #335) FOUND 4"X 4"X 60" POST SOUTH 1.5'. (NOW GONE).

SURVEYS AND REWITNESSES OF RECORD

T.C.S. REWITNESS BOOK 5 PAGE 60	10-27-70	JOHN L. CARLICH	LS 287
FIELD BOOK P5 PAGE 53	MARCH 1928	WILLIAM E ANDERSON	
B-45	MARCH 1928	WILLIAM E ANDERSON	
B-243	JANUARY 1926	W. S. COATES	
B-659	04-08-75	KARL FOESTE	LS 849
REWITNESS CARD 335	11-04-77	JOHN L. CARLICH	LS 287
BOOK 4 PAGE 75	APRIL 1950	W. E. ANDERSON	C. S.
FIELD NOTEBOOK 1 PAGE 88	APRIL 1950	W. E. ANDERSON	C. S.

LOCATION OF MONUMENT

THIS CORNER IS LOCATED APPROXIMATELY 100' SOUTH A GRAVEL LOGGING ROAD AND APPROXIMATELY 700' NORTH OF OREGON STATE HIGHWAY 131 IN A RECENT CLEARCUT.


NEW ACCESSORIES

\*HAT SECTION POST N.20°W 1.70'

IN THE PRESENCE OF AL DVORAK JOE JENSEN AND DAN MCNUTT

May 8, 2002

TITLE:



*Allan E Duncan, C.S.*



*RENEWAL 12/31/03*



PAGE 2 OF 2

BOOK 7 349