

CHAINS

Township 1 NORTH Range 8 West

Section corner — 35-36 B. L. R. 8 W.

Original Hemlock S. 63° E. 22 links, blaze chopped out and partially burnt. Orig. Spruce S. 78° W. is a Hemlock. Blaze chopped out and badly burnt. Orig. Hemlock N. 22° E. 26 links blaze chopped out and in good condition. Orig. Hem. N. 33° W. 33 links is gone except for a piece of stump on the root of which we cut out B. T. Set 3.5' piece of 2" pipe 3' in ground with a squared cedar stake. On orig. S. 63° E. 14.5 - new blaze below old marked B. L. R. 8 W. On orig. Hem. S. 78° W 15.6 new blaze below old marked--T. 1 S. R. 8 W. B. T.

2-18-42

Closing corner Sec. 1-2 B. L. R. 8 W.

Orig. Hem. N. 55° E. 20 links, blaze chopped out and burnt. We cut out B. T. Orig. Hem. S. 21° W. 24 links, tree broken off and badly burnt; half of 8 is all of scribing left. Orig. Hem. S. 24° 30' E. 80 links; blaze chopped out and all marks burnt. Set 30" of 2" iron pipe 24" in ground, with squared cedar stake. 52" fire killed fir bears S. 15° 30' E. 10.0 marked--C. C. S. 1 2 T. 1 S. R. 8 W. B. T. 48" fire killed fir bears N. 44° W. 25.6 marked--C. C. 1-2 T. 1 S. R. 8 W. B. T. 52" fire killed fir bears N. 53° E. 20.5 marked--C. C. 1, 2 T. 1 S. R. 8 W. B. T.

2-18-42

Quarter corner between 1-2 T. 1 S. R. 8 W.

Orig. Hem. S. 45° W. 10 links, blaze chopped out and badly burnt; two iron marks still visible. Orig. 40" fir N. 48° E. 57 links; blaze chopped out and all marks burnt except cruiser marks. New blaze on orig. fir (now stump) marked 1/4 B. T. 84" fir stump N. 3.2 marked 1/4 B. T. 72" fir stump S. 6° W. 33.0 marked--1/4 B.T. Set 8' piece of 1" pipe 6' in ground.

1-31-42

Section corner 1-2-11-12 T. 1 S. R. 8 W.

Orig. 5" hem. (now about 6") N. 56° W. 15 links. Found short piece of orig. stump laying down hill it had been knocked down a few years after it was blazed. Bottom of blaze with tail of T. was all that was left. Orig. 6" hem. N. 61° E. 47 links was a short stump with a big hole at the blaze. Above the hole we chopped out cruiser mark in shape of perfect star. Orig. 8" hem. S. 57° W. 58 links down and badly burnt. Found cruiser mark in shape of W. Set 3.5' piece of 1 1/4" iron pipe 3' in ground with a 3' piece of 3/4" iron rod inside. 30" dead hemlock snag bears S. 84° W. 8.4 marked; T. 1 S. R. 8 W. 1-2-11-12 B. T. 1/2" dowel in root of burnt out 60" fir stump bears N. 2° 30' E. 18.1.

1-29-42

Quarter corner between 11-12 T. 1 S. R. 8 W.

Found truck axle hub end flush with ground. Bearing trees set by Anderson are burnt out. Set a 48" fire killed fir bears N. 30° 30' W. 38.1 marked 1/4 B. T. A 60" fire killed fir bears S. 69° E. 9.2 marked 1/4 B. T. A 50" fire killed fir bears S. 80° W. 33.0 marked 1/4 B. T.

1-20-42

SE 35  
LN 8.

N.W-1  
LS 8.

W. B. RY  
LS 8.

SW 1  
LS 8.

E B. RY  
11-152