

| CHAINS   |   |
|----------|---|
| 39+83.6  | <p>We also set a 4" x 4" white guard post stenciled CENTER SEC. on 2 faces and O.S.H. PROP. COR. on other 2 faces in black. No live trees available for bearing trees.</p>  |
| 52,95.9  | <p>3/4" x 30" iron pin for the East 1/16 corner on the E.&amp;W. centerline of the section, with 4" x 4" white guard post stenciled 1/16 SEC. COR. on 2 faces and O.S.H. PROP. COR. on other 2 faces in black.</p>  |
| 13+32.9  | <p>The quarter corner on the line between sections 3 and 2, previously described. <i>see pg. 20</i></p>   |
| 13-24.5  | <p>Returning to the South 1/16 corner on the N.&amp;S. centerline of section 3.</p>   |
| 13-12.1  | <p>Thence N. 89° 19 1/2' W. toward the center of the S.W. quarter of Sec. 3.</p>  |
| 26, 24.2 | <p>3/4" x 30" iron pin for the center of the S. W. 1/4 of section 3, with 4" x 4" white guard post stenciled 1/16 SEC. COR. on 2 faces and O.S.H. PROP. COR. on other 2 faces in black.</p>   |
|          | <p>Thence N. 0° 19' W. between the East and West halves of the S. W. quarter of section 3.</p>  |
|          | <p>The West 1/16 corner on the E. &amp; W. centerline of the section.</p>   |
|          | <p>Returning to the North 1/16 corner on the N.&amp;S. centerline of section 3, we ran thence,</p>  |
|          | <p>S. 89° 21 1/2' E. between the North and South halves of the N. W. quarter of section 3.</p>  |
|          | <p>3/4" x 30" iron pin for the center of the N.W. 1/4 of section 3, with a 4" x 4" white guard post stenciled 1/16 SEC. COR. on 2 faces and O.S.H. PROP. COR. on other 2 faces in black.</p>  |
|          | <p>The North 1/16 corner on the line between sections 3 and 2, previously</p>   |
|          | <p>From the corner to sections 32-33-5-4 on the line between townships 3 and 4 North, R. 6 W., previously described, we ran Southerly by traverse to the quarter corner between sections 5 and 4.</p>   |
|          | <p>At a point 2151.9 ft. S. 0° 16' W. of the section corner, in a small area untouched by fire, we found an old 4" x 4" scribed stake still in place, and both original bearing trees at proper distances. Scribing shows plainly but both trees dead. We replace the stake with a 2" x 48" galv. iron pipe with brass cap on which is stamped a line with short cross mark and, circumferentially, 1/4 COR. T. 3 N. R. 6 W.W.M. - O.S.H.D. We also set a 4" x 4" white guard post stenciled 1/4 SEC. COR. on 2 faces in black, and marked 2 new bearing trees, as follows:</p>   |
|          | <p>An 18" hemlock bears S. 11° W. 80.0 ft., scribed 1/4 S. B.T.<br/>A 14" cedar bears S. 38° E. 58.0 ft., scribed 1/4 S. B.T.</p>   |
|          | <p>Returning to the corner to sections 4-3-9-10, we ran Westerly by traverse to the quarter corner between sections 4 and 9.</p>  |
|          | <p>At a point 2633.9 ft. S. 88° 50' W. of the section corner, we found a stone with 1/4 cut into the North face, with a 36" green fir N. 4° W. 101.0 ft., and a 36" larch snag S. 48° W. 75 ft. Leaving the stone undisturbed, we set a 2" x 48" galv. iron pipe at a point 0.4 ft. West and 0.1 ft. North of the cross on the stone. The pipe has a brass cap on which is stamped a line with short cross mark and the numbers 4 and 9 and, circumferentially, 1/4 COR. T. 3 N. R. 6 W.W.M. - O.S.H.D. We set a 4"x4" white guard post stenciled 1/4 SEC. COR. on 2 faces in black, and marked two new bearing trees, as follows: <i>SEE PAGE 25</i></p> |

R. CEN.

1/16-COR.  
3-3.N.6.

1/16-COR.  
3-3.N.6.

1/16-COR.  
3-3.N.6.

1/16-COR.

1/4 COR.  
45-3.N.6.

1/4-COR.  
49-3.N.6.

Book I