

104

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 3 and 34,
Townships 1 and 2 North, Range 6 West, W.M.,
Tillamook County, Oregon.

ORIGINAL

Stone 12" x 12" x 6" found in place, $\frac{1}{4}$ on NE face,
from which a:

18" Cedar bears North 1 lk.;
now 24" burnt stump.

RESTORED

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze
cap marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ S34 S3
1953 2311," 30 inches in ground, on North edge original
stone, in mound of stone, and from which a:

46" Cedar stump bears S32 $\frac{1}{2}$ °W 49.7 ft.,
scribed $\frac{1}{4}$ S3 BT
31" Fir stump bears N61°E 18.7 ft.;
scribed $\frac{1}{4}$ S 34 BT RE 2311.

Oregon State Board of Forestry metal location poster on
31" Fir stump BT.


Also poster on white Cedar post 686.8 ft. East on fire
break access road.

Also poster on white Cedar post 1791.7 ft. East on
Rutherford Road.

Also white Cedar post 3 ft. SE of pipe.

Dated December 17, 1953.

Restored by Richard Morris under my
direction. Richard Morris, Compassman



Present and witnessed by Lloyd Geraths
Alan Ramage

Book I