

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 19, 30, 24 and 25,
Township 2 North, Ranges 9 and 10 West, W.M.,
Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 8" Fir bears S42°E 24 lks.; now 12" broken off stub 3 ft. high, BT scribes visible, cast of S visible on broken off portion.
- 5" Fir bears N85°E 23 lks.; now 18", in place, face grown over.
- 3" Fir bears S25°W 14 lks.; now 9" stub 3 ft. high, BT scribes visible, S25 scribes visible on broken off piece.

RESTORATION by W. A. Markham (no date given)

Set 1/2" x 43" iron pipe (now in good shape, but out of place - it bears N73°W 15.4 ft. from true corner point), from which a:

- 30" Fir bears S50°W 17.0 ft.; bark scribed according to records, but found S25 BT scribed in wood and partly grown over.

RESTORED

Set 1 1/2" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T2N R10W R9W S19 S30 S24 S25 1954 RE 2311," 32 inches in ground, over top of 1/2" x 43" pipe which I put at true corner point by consent of County surveyor and W. A. Markham, in small mound of stone, and from which a:

- 30" Fir bears S77°W 28.1 ft.; scribed S25 BT (by Markham)
- 30" Fir bears N20°W 26.0 ft.; scribed T2N R10W S24 BT RE 2311.
- 14" Fir bears S52°E 22.0 ft.; scribed T2N R9W S30 BT.
- 20" Fir bears N37°E 40.0 ft.; scribed T2N R9W S19 BT.

Oregon State Board of Forestry metal location poster on 5" Hemlock N69°W 20.1 feet.
4" x 4" x 72" white Cedar post 1 ft. NW of pipe.

April 21, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Compassman



Book I

Present and witnessed by Robert Cowan, Lloyd Geraths
Arnold G. Gibson