

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 27 and 28, Township 3 North, Range 6 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which :

36" Cedar bears N35½°W 39 lks.; now 36" stump, original axe mark, bottom of face.

30" Hemlock bears N71°40'E 57.5 lks.; now 24" stump, outer edges of original face remaining.

40.20 chains leaning Hemlock line tree; now 14", down and rotted, roots in place.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S28 S27 1954 RE 2311,"

32 inches in ground, in mound of stone, and from which as:

7" Fir bears N50°W 9.2 ft.; scribed 1/4 S28 BT RE 2311.

7" Fir bears N80°E 14.5 ft.; scribed 1/4 S27 BT.

Oregon State Board of Forestry metal location poster on 7" Fir BT N80°E.

4" x 4" x 72" white Cedar post 1 ft. SE of pipe.

Also poster on 7" Fir on N. edge log road 186.2 ft. N of Corner.

Dated April 15, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Compassman



Present and witnessed by Robert Cowan
Lloyd Geraths