119

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 14, 15, 22 and 23, Township 3 North, Range 6 West, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 40" Fir bears N46°E 63 lks.; now 36" stump, scribed T3N R6W S14 BT visible.
- 48" Fir bears Sll°E 23 lks.; now 24" uproot, RóW scribes visible, roots in place.
- R6W scribes visible, roots in place.
 48th Fir bears S54½°W 29 lks.; now 36th stump, old face visible, scribes burnt off.
- 24" Hemlock bears N2 W 61 lks.; now 24" down and out of place, portions of scribes visible, roots in place.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R6W S15 S14 S22 S23 1954 RE 2311," 32 inches in ground, in mound of stone, and from which a:

- 7" Fir bears N84°W 149.1 ft.; scribed T3N R6W S15 BT RE 2311.
- 6" Fir bears $S2\frac{1}{2}$ °E 164.5 ft.; scribed T3N R6W S23 BT.
- 24" Fir stub 6 ft. high bears S49°W 720 ft.; scribed T3N R6W S22 BT.

Oregon State Board of Forestry metal location poster on original 48th Fir BT.

Also poster on 48th Fir stump on South edge fire break road 165 ft. N. of corner.

 $4^{11} \times 6^{11} \times 72^{12}$ white Cedar post 1 ft. NW of pipe.

Dated April 15, 1954.

Restored by

March March under my direction.

STERED PROFESSION CONTROL 2311

OCCUPANTION TO THE PROPERTY OF THE PROPERTY OF

Present and witnessed by Robert Cowan and L'Loyd Geraths

Book I