

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 14, 15, 22
and 23, Township 3 North, Range 7 West, W.M.,
Tillamook County, Oregon.

ORIGINAL

Stone 20" x 12" x 10" in place 15" in ground with
3 notches on South edge and 2 notches on East
edge from which a:

- 60" Fir bears N63°E 35 lks.; now 56" snag
scribes T3N R7W S14 visible, rest not
cut out.
- 9" Hemlock bears S45°E 20 lks.; now 9"
rotted stub 3 ft. high, BT scribes visible.
- 20" Hemlock bears S9°W 52 lks.; now missing,
point falls on top of cliff.
- 24" Hemlock bears N68°W 26 lks.; now 32" stub
20 ft. high scribes 3N R7W S visible.

RESTORED

Placed 18" x 12" x 10" stone along side original
stone from which a:


- 6" Fir bears N18°W 10.9 ft.; scribed T3N R7W
S15 BT RE 2311.
- 5" Hemlock bears N67°E 26.3 ft.; scribed T3N
R7W S14 BT.
- 5" Hemlock bears S51°E 29.5 ft.; scribed T3N
R7W S23 BT.
- 5" Fir bears S15°W 12.4 ft.; scribed T3N R7W
S22 BT.

Oregon State Board of Forestry metal location poster
on 6" Fir BT.

4" x 4" x 60" white Cedar post 1.5 ft. SW of pipe.

Dated March 19, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Compassman



Present and witnessed by Alan Ramage, Lloyd Geraths
Robert Cowan