

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 13 and 14,
Township 3 North, Range 7 West, W.M., Tilla-
mook County, Oregon

ORIGINAL

Post, now rotted and on ground, scribes visible, point
found in ground in place, from which a:

- 6" Hemlock bears S73°W 12 lks.; now missing.
- 20" Hemlock bears S65°E 16 lks.; now 26" stump,
scribes $\frac{1}{2}$ visible, rest not cut out.

RESTORED

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY 1/4 S14 S13
1954 RE 2311," 34 inches in ground, in mound of stone
3' x 3' x 10", and from which a:

- 53" Fir stump bears S44°E 11.2 ft.; scribed 1/4 S13
BT RE 2311.
- 52" Fir stump bears N10°W 16.2 fr.; scribed 1/4 S14
BT.

Oregon State Board of Forestry metal location poster on 52"
fir stump BT.
Also poster on 53" Fir stump BT.
Also poster on 36" Fir stub on south edge log road 970.0 ft.
south of corner.
4" x 4" x 72" white Cedar post lft. NE of pipe.

Dated March 24, 1954

Restored by Richard Morris under my direction.
Richard Morris, Compassman



Present and witnessed by: Robert Cowan, Alan Ramage, Lloyd Geraths.