CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 10, 11,14 and 15 Township 1 South, Range 8 West, W.M., Tillamook County, Oregon.

n traditi

ORIGINAL

 $18^{11}~\text{x}~10^{11}~\text{x}~10^{11}$ stone, now missing, from which a:

Hemlock bears N52°W 4 lks.; now missing. Hemlock bears N42°E 3 lks.; now missing.

20 Hemlock bears S20°E 19 lks.; now missing, slide area.

8" Hemlock bears S66°W 64 lks.; now missing.

RESTORATION by W. E. Anderson, December 21, 1931.

 $4^{11} \times 4^{11} \times 30^{11}$ Fir limb, SC scribed on one side, now down and out of place, from which a:

8th Hemlock bears N83°W 59.0 ft.; now missing. 16th Hemlock bears N38°W 60.7 ft.; now missing. 24th Hemlock bears N70°E 34.8 ft.; now 31th stub 30 ft. high, BT SC scribes visible.

RESTORED

Set $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked, "OREGON STATE BOARD OF FORESTRY TIS ROW SIO SII SI5 SI4 1954 RE 2311," 32 inches in ground, in small mound of stone, and from which a:

- 61t Alder bears N83 W 50.0 ft.; scribed TLS R8W S10 BT.
- Alder bears S652°W 44.3 ft.; scribed T1S R8W S15 BT RE 2311.
- 6" Alder bears S412°E 48.0 ft.; scribed TIS RSW S14 BT.
- Spruce bears N73°E 85.3 ft.; scribed TLS R8W S11 BT.

Oregon State Board of Forestry metal location poster on 6th Alder BT S413°E.

Also poster on 24" Hemlock N70°E.

Also poster on 4" x 4" x 48" white Cedar post on East edge Trask. cut off road approx. 660' West of corner. 4" x 4" x 60" white Cedar post 1.5' SE of pipe.

Dated March 19, 1954.

Restored by

Richard Morris,

under my direction.

RED PROFES MGINEER

Present and witnessed by Lloyd Geraths

Book I