

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 22, 23, 26 and 27, T2N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

14"x12"x8" stone, 2 notches on S and 2 on E sides, now in place, from which a:

- 49" Hemlock bears N41°E 105 lks.; position covered by pile of logs.
- 52" Hemlock bears S40°E 63 lks.; now 50" rotted stump.
- 19" Hemlock bears S21°W 17 lks.; now 18" stump, edges of original face remaining.
- 33" Hemlock bears N45°W 8 lks.; now 36" stump, lower edge of original face remaining.

RESTORED

Erected mound of rock around corner stone, from which a:

- 11" Hemlock bears S5°W 99.0 ft.; scribed T2N R8W S27 BT.
- 11" Hemlock bears S22°E 144.3 ft.; scribed T2N R8W S26 BT RE 2311.

Rock outcrop 30' by 30' bears N6°W 151.0 ft.; scribed B0.

Oregon State Board of Forestry metal location poster on 11" Hemlock BT S22E.

Oregon State Board of Forestry metal location poster on 24" Hemlock stub 150 ft. East, on East edge FB road. Set 4"x4"x84" white Cedar post 2 ft. SE of stove.

Dated December 8, 1954.

Restored by Richard Morris under my direction.  
Richard Morris, Engr. Aide



Present and witnessed by Claude Weikel  
Forrest Logan  
Lloyd Geraths

Book I