

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 9,10,15 and 16, T3N R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 18"x10"x4", now in place, 3 notches on E edge and 4 on S, from which a:

- 6" Hemlock bears N2°E 48 lks.; now missing, position covered by uprooted Fir.
- 15" Hemlock bears S40°E 27 lks.; now 7" stub, 4' high, scribes BT visible, rest rotted away.
- 12" Hemlock bears S68°W 26 lks.; now 11" stub, 4' high, upper face burnt out, portion of scribe BT visible.
- 30" Hemlock bears N52°W 88 lks.; now 36" stub, 10' high, face and scribes rotted away.

RESTORED

Left Original stone in place with 1"x5' Iron pipe on E edge, 18 inches in ground, in mound of stone, and from which a:

- 5" Fir bears N73°E 40.6 ft.; scribed T3N R7W S10 BT RE 2311.
- 5" Noble fir bears S68°E 33.2 ft.; scribed T3N R7W S15 BT.
- 5" Fir bears N68°W 8.5 ft.; scribed T3N R7W S9 BT.
- 5" Hemlock bears S19°W 9.0 ft.; scribed T3N R7W S16 BT.

Oregon State Board of Forestry metal location poster on 5" Hem. BT.
Set 4"x4"x72" White Cedar post 3 ft. NW of corner stone.

Dated November 24, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Engr. Aide



Present and witnessed by Lloyd Geraths
Forest Logan
Claude Weikel