

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 15,16,21 and 22 T3N,
R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 18"x10"x9", (found stone in place, no notches)
from which a:

- 36" Hemlock bears N42°E 61 lks.; now 48" stump, face and scribes apparently cut off when logged.
- 10" Hemlock bears S80°E 47 lks.; now missing, position falls in slide area.
- 16" Hemlock bears S33°W 33 lks.; now 16" uprooted, root hole in place, laying on face side.
- 24" Spruce bears N58°W 48 lks.; now 40" stump, scribe B visible, upper face cut off when logged.

RESTORED

Set 1½" x 40" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R7W S15 S16 S21 S22 1954 RE 2311," 36 inches in ground, in mound of stone, and from which a:

- 40" Fir stump bears S22½°E 48.0 ft.; scribed T3N R7W S22 BT RE 2311.
- 38" Fir stump bears S82°W 46.1 ft.; scribed T3N R7W S21 BT.
- 37" Fir stump bears N77°E 118.4 ft.; scribed T3N R7W S15 BT.
- 42" Fir stump bears N55½°W 105.8 ft.; scribed T3N R7W S16 BT.

Oregon State Board of Forestry metal location poster on 40" Fir stump BT.

Set 4"x4"x72" white Cedar post ~~set~~ 1 ft. SE of pipe.

Oregon State Board of Forestry metal location poster on 48" Hemlock stump 9 ft. W of pipe.

Dated November 23, 1954.

Restored by Richard Morris under my direction.
Richard Morris, Engr. Aide



Present and witnessed by Lloyd Geraths, Claude Weikel and Forest Logan