

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 23 and 24,  
T2N, R7W, W.M., Tillamook County, Oregon

ORIGINAL

Basalt stone 19"x10"x9", now missing (slide area) from which a:

16" Hemlock bears N62 $\frac{1}{2}$ °E 35 lks.; now 16" 10 ft. high  
stub, S visible on burnt face, BT face unexposed.

8" Hemlock bears N59°W 14 lks.; now missing (slide area).

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY  $\frac{1}{4}$  S23 S24 1954 RE 2311,"  
26 inches in ground, in mound of stone, and from which a:

27" Fir bears N48°E 39.8 ft.; scribed  $\frac{1}{4}$  S24 BT RE 2311.  
Rock face 10'x4' high bears S27°W 5.2 ft.; scribed BO.


Oregon State Board of Forestry metal location poster on  
Original 16" Hemlock BT.

Oregon State Board of Forestry metal location poster on  
27" Fir BT.

Set 4"x3"x72" white Cedar post 1.5 ft. SW of pipe.

Dated November 17, 1954.

Restored by Richard Morris under my direction.  
Richard Morris, Engr. Aide.



Present and witnessed by Claude Weikel  
Forest Logan