

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 25 and 26,  
T2N, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 18"x10"x8"  $\frac{1}{4}$  on W face now in place from which as:

26" Hemlock bears N71°E 11 lks.; now 25" 50 ft. high  
stub, BT scribes remaining.

30" Hemlock bears S79°W 41 lks.; now 32" 50 ft. high  
stub, portion of T scribe remaining.

RESTORED

Erected mound of rock around corner stone, from which as:

36" Fir snag bears N27°E 97.2 ft.; scribed  $\frac{1}{4}$  S25 BT.

49" Fir snag bears N85 $\frac{1}{2}$ °W 18.5 ft.; scribed  $\frac{1}{4}$  S26 BT  
RE 2311.

Oregon State Board of Forestry metal location poster on  
49" Fir snag BT.

Set 3"x3"x72" white Cedar post 1 ft. SE of pipe.

Dated November 18, 1954.

Restored by Richard Morris under my direction.  
Richard Morris, Engr. Aide



Present and witnessed by Forest Logan  
Claude Weikel