

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 8 and 9  
T1S, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

18"x12"x9" stone, now in place,  $\frac{1}{4}$  on West side, from which a:

8" Hemlock bears N37°W 47 lks.; now 10" by 4" rotted  
stub on ground, roots in ground in place.

5" Maple bears N31°E 18 lks.; just roots remaining  
in place.

RESTORED

Erected mound of rock around corner stone, from which a:

14" Fir bears N77 $\frac{1}{2}$ °W 26.4 ft.; scribed  $\frac{1}{4}$  S8 BT.

28" Spruce bears N31°E 19.5 ft.; scribed  $\frac{1}{4}$  S9 BT RE 2311.

Oregon State Board of Forestry metal location poster on  
14" Fir BT.

Oregon State Board of Forestry metal location poster on  
4"x4"x84" white Cedar post 261.0 ft. N on N side  
Wilson River Highway.

Set 4"x4"x84" White Cedar post 2 ft. NW of stone.

Dated December 14, 1954.

Restored by Arnold G. Gibson under my direction.  
Arnold G. Gibson Ass't. Engr.



Present and witnessed by Richard Morris  
Floyd Geraths  
Forest Logan  
Claude Weikel