

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 9, 10, 15 and 16,  
T2N, R8W. W.M., Tillamook County, Oregon

ORIGINAL

12"x7"x6" stone, now in place with 5 notches on S and 3  
on E sides, from which a:

- 18" Hemlock bears N53°E 29 lks.; now 30" stub 3 ft.  
high, badly rotted.
- 5" Hemlock bears S11°E 55 lks.; now missing, point  
falls in slide area.
- 12" Hemlock bears S77°W 26 lks.; now just roots remaining  
in place.
- 14" Hemlock bears N27°W 79 lks.; now 11" stub 4 ft.  
high, badly rotted.

RESTORED

Erected mound of rock around original stone, from which a:

- 70" Cedar stump bears S7°W 24.8 ft.; scribed T2N  
R8W S16 BT.
- 63" Fir snag bears S12°E 104.3 ft.; scribed T2N  
R8W S16 BT RE 2311.
- 4" Alder bears N23°W 34.8 ft.; scribed X BT.
- 4" Alder bears N15°E 54.3 ft.; scribed X BT.

Oregon State Board of Forestry metal location poster on  
70" Cedar stump.

Oregon State Board of Forestry metal location poster on  
6" Alder 400 ft. S55°W on East side log road.

Set 4"x4"x84" white Cedar post 1.5 ft. NW of corner.

Dated December 14, 1954.

Restored by Richard Morris under my direction.  
Richard Morris, Eng. aide



Present and witnessed by Claude Weikel and Lloyd Geraths