

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Section corner common to Sections 16, 15, 21 and 22  
T2N, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

16"x9"x5" stone, now in place with 3 notches on E and 3  
on S sides, from which a:

- 24" Hemlock bears N24°E 9 lks.; now 38" snag BT  
scribes remaining.
- 18" Hemlock bears S59°E 53 lks.; now 30" stub 15 ft.  
high, edge of burnt face remaining.
- 16" Hemlock bears S56°W 53 lks.; now 24" stub 8 ft.  
high, edge of burnt face remaining.
- 8" Hemlock bears N8°W 70 lks.; now 10" stub 3 ft.  
high badly burnt.

RESTORED

Erected mound of rock around corner stone, from which a:

- 41" Fir stub 25 ft. high bears N32°W 28.2 ft.; scribed  
T2N R8W S16 BT RE 2311.
- 50" Fir stump bears N73°E 106.7 ft.; scribed T2N R8W  
S15 BT.
- 42" Fir stump bears S38°E 106.1 ft.; scribed T2N R8W  
S22 BT.
- 52" Fir stump bears S80°W 83.9 ft.; scribed T2N R8W  
S21 BT.

Oregon State Board of Forestry metal location poster on  
52" Fir stump BT.

Oregon State Board of Forestry metal location poster on  
original 24" Hemlock BT.


Oregon State Board of Forestry metal location poster on  
original 16" Hemlock BT.

Oregon State Board of Forestry metal location poster on  
24" Hemlock stub 550 ft. N. on S edge log road.

Set 4"x4"x82" white Cedar post 1 ft. SW of corner.

Dated December 14, 1954.

Restored by Richard Morris under my direction.  
Richard Morris, Engr. Aide



Present and witnessed by Claude Weikel and Lloyd Geraths