

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One Quarter - Section corner common to Sections 15 and 22 T3N, R7W, W.M., Tillamook County, Oregon.

ORIGINAL

Stone 18" x 16" x 12", now missing, from which a:

24" Fir bears S18°E 14 lks.; now 24" uprooted stump, root hole in place, part of scribe BT visible, rest missing.

24" Fir bears N8°E 6 lks.; now 24" uprooted stump, root hole in place, scribes and face rotted away.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY 1/4 S15 S22 1954 RE2311," 32" in ground, in mound of stone, and from which a:

6" Fir bears S 61°E 14.5 ft.; scribed 1/4 S22 BT RE2311

7" Fir bears N 63°W 60.6 ft.; scribed 1/4 S15 BT.

Oregon State Board of Forestry metal location poster on 6" Fir BT.

Set 4" x 4" x 84" White Cedar post 1 ft. SW of pipe.

Dated December 31, 1954

Restored by Richard Morris under my direction
Richard Morris, Engr. Aide



Present and witnessed by Forrest Logan
Claude Weikel
Lloyd Geraths