

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Baseline Section corner common to Sections 32 and 33,  
TLN, R8W, W.M., Tillamook County, Oregon.

ORIGINAL

Stone 22" x 10" x 6", now missing (found 7" Alder growing  
in place), from which a:

- 14" Hemlock bears North 37 lks.; now 13" stub, 6' high,  
scribes BT visible, rest rotted away.
- 66" Cedar bears North 43°E 20 lks.; now 70" snag with  
old burnt out face, no scribes remaining.

RESTORED

Bark scribed the 7" Alder TLN R8W EL on N side, S32 on W,  
and S33 on E, from which a:

- 6" Alder bears N14°W 10.9 ft.; bark scribed TLN R8W S32 BT.
- 78" Cedar snag bears N34°E 48.4 ft.; scribed TLN R8W S33  
BT RE 2311.

Oregon State Board of Forestry metal location poster on 7"  
Alder corner tree.

Oregon State Board of Forestry metal location poster on 90"  
Cedar snag S42°E 20.5 ft.

Set 4" x 4" x 70" White Cedar post 4 ft. S of cor. tree.

Dated January 17, 1955.

Restored by Richard Morris under my direction.  
Richard Morris, Engr. Aide



Present and witnessed by Claude Weikel  
Forest Logan