

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Closing corner common to Sections 4 and 5, T1S, R8W, W.M.,
Tillamook County, Oregon.

ORIGINAL

Post, now missing from which a:

- 80" Spruce bears S34 $\frac{1}{2}$ °W 14 lks.; now 80" uproot,
large root in place with scribes BT on it,
scribes T1S W found on chunk on ground.
- 16" Hemlock bears S33 $\frac{1}{2}$ °E 24 lks.; now missing,
Spruce BT uproot fell on its position.
- 8" Hemlock bears N7°E 17 lks.; now missing,
point falls in slide area.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked
"OREGON STATE BOARD OF FORESTRY T1N S33 S5 S4 T1S R8W
/ cc 1955 RE 2311," 34 inches in ground, in mound of
stone, and from which a:

- 30" Cedar bears S41°W 75.1 ft.; scribed CC T1S R8W
S5 BT RE 2311.
- 8" Alder bears S11°E 45.9 ft.; bark scribed CC T1S
R8W S4 BT.

Oregon State Board of Forestry metal location poster on 5"
Alder N7°W 19.5 ft.

Set 4" x 4" x 72" white Cedar post 1 ft. NE of pipe.

Dated January 17, 1955.

Restored by Richard Morris under my direction.
Richard Morris, Engr. Aide



Present and witnessed by Claude Weikel