

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One-quarter section corner common to W. boundary of Section 18,
T. 1S, R. 8W, W.M., Tillamook County, Oregon.

ORIGINAL

Basalt stone 14" x 10" x 9", now 18" x 12" x 11" in
place, no marks visible, from which a:

8" Alder bears N73°W 40 lks.; now 30" in diameter,
face rotted out.

30" Hemlock bears N40°E 48 lks.; now 54" in diameter,
scribes $\frac{1}{4}$ " S BT visible.

RESTORED

Set 1 $\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY $\frac{1}{4}$ " S18 1955 RE2311,"
30 inches in ground, in mound of stone, with original
stone on N edge, and from which a:

56" Hemlock bears N55°E 63.3 ft.; scribed $\frac{1}{4}$ " S18 BT RE 2311.

Oregon State Board of Forestry metal location poster on
Original 54" Hemlock BT.

Set 4" x 4" x 60" white Cedar post 4' SE of pipe.

January 24, 1955.

Restored by Richard Morris under my direction.
Richard Morris, Engr. Aide



Present and witnessed by Lloyd Geraths
Claude Weikek
Forest Logan