

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Closing section corner common to Sections 6 and 7,  
T3N R6W W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 32" Hemlock bears N23½°E 28½ lks.; now just roots and root hole in place.
- 14" Hemlock bears S18°10'E 64½ lks.; now just roots and root hole in place.
- 16" Hemlock bears S27°W 25½ lks.; now 26" snag, part of scribes T3N R W S visible on edge of burnt out face.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N S1 S6 S7 CC R6W.1955 RE 2311," 32 inches in ground, in mound of stone, and from which a:

- 66" Fir stump bears S39°E 65.6 ft.; scribed T3N R6W S7 CC BT.
- 48" Fir stump bears N44½°E 40.2 ft.; scribed T3N R6W S6 CC BT RE 2311.

Set 4"x4"x60" white Cedar post 1.5' W of pipe.  
Oregon State Board of Forestry metal location poster on 48" Fir stump BT.  
Oregon State Board of Forestry metal location poster on 4"x4"x60" white Cedar post on W edge Rd. approx. 420' E.

Dated February 21, 1955

Restored by Richard Morris under my direction.  
Richard Morris, Engr. Aide



Present and witnessed by Claude Weikel  
Forrest Logan  
Lloyd Geraths