

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Sections 19 and 20, T. 2N,
R. 7W., W.M., Tillamook County, Oregon.

ORIGINAL

Stone 18"x9"x5", now missing, from which a:

36" Hemlock bears N78°W 44 lks.; now large roots
remaining.

42" Fir bears S50°E 118 lks.; now 70" stump, scribes
BT remaining.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap
marked "OREGON STATE BOARD OF FORESTRY ¼ S19 S20
1955 RE 2311," 33 inches in ground, in mound of
stone, and from which a:

54" Fir stump bears S28°E 59.3 ft.; scribed ¼ S 20
BT RE 2311.

80" Hollow Fir stub bears S87½°W 43.0 feet; scribed
¼ S 19 BT.

Set 3"x3"x72" white painted Cedar post 3 ft. West of pipe.
Oregon State Board of Forestry metal location poster on
80" Fir stub BT.

Also poster on 42" Fir stump BT.

Dated May 17, 1955

Restored by Arnold G. Gibson under my direction.
Arnold G. Gibson, Assistant Engineer



Present and witnessed by Richard Morris
Forrest Logan
Lloyd Geraths
Robert Sturm