

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Section 12 (East side)  
T3N, R7W, W.M., Tillamook County, Oregon

ORIGINAL

Stone 14"x10"x6", now broken up and in place with  $\frac{1}{4}$  on W face  
from which a:

- 30" Fir bears West 11 lks.; now 31" stump, badly burnt.
- 5" V. Maple bears S53°E 36 lks.; now missing, Vine Maple  
clumps in vicinity.

RESTORED

Set  $1\frac{1}{2}$ " x 36" galvanized iron pipe with 3" bronze cap marked  
"OREGON STATE BOARD OF FORESTRY  $\frac{1}{4}$  S12 1955 RE2311," 34 inches  
in ground with pieces of  $\frac{1}{4}$  stone on N edge pipe in mound of  
stone, and from which a:

55" Fir stump bears N31°W 57.8 ft.; scribed  $\frac{1}{4}$  S12 BT RE2311.

Oregon State Board of Forestry metal location poster on 32" Fir  
snag N68°W 27.6 ft.

Set 4"x4"x72" white painted Cedar post 1 ft. NE of pipe.

Dated May 31, 1955.

Restored by Richard Morris under my direction.  
Richard Morris, Engineering Aide



Present and witnessed by Lloyd Geraths  
Robert Sturm  
Forrest Logan