

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

Closing corner common to Sections 7 and 18, T3N, R6W, W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

- 12" Hemlock bears N64°E 17 lks.; roots remaining in place.
- 30" Hemlock bears S81¹⁰/₂°E 23 lks.; now 36" snag, portions of scribes R6W BT remaining.
- 40" Fir bears S82¹⁰/₂°W 16 lks.; now 36" uproot, downhill out of place, badly burnt, roots and root hole in place.

RESTORED

Set 1¹/₂" x 36" galvanized iron pipe with 3" bronze cap marked "OREGON STATE BOARD OF FORESTRY T3N R6W R7W S12 S7 S18 CC 1955 RE2311," 33 inches in ground, in mound of stone, and from which a:


- 35" Fir stump bears N58°E 17.3 ft.; scribed CC T3N R6W S7 BT RE2311.
- 48" Fir stump bears S1°E 63.4 ft.; scribed CC T3N R6W S18 BT.

Oregon State Board of Forestry metal location poster on 35" Fir stump BT.

Set 4"x4"x60" white painted Cedar post 1 ft. NW of pipe. Also poster on 12" Fir on W edge road 1550 ft. East.

Dated May 31, 1955.

Restored by Richard Morris under my direction.
Richard Morris, Engineering Aide



Present and witnessed by Forrest Logan
Robert Sturm
Lloyd Geraths