

CHAINS

RESTORED CORNER FOR OREGON STATE BOARD OF FORESTRY

One quarter corner common to Section 7 (West side)  
T. 1 S., R. 8 W., W.M., Tillamook County, Oregon.

ORIGINAL

Post, now missing, from which a:

18" Hemlock bears S59°W 13 lks.; now 42" chopped  
out S scribe, remainder unexposed.

10" Hemlock bears N62°E 38 lks.; now 10" 5 ft. high  
rotted stub.

RESTORED

Set 1½" x 36" galvanized iron pipe with 3" bronze cap  
marked "OREGON STATE BOARD OF FORESTRY ¼ S7 1955  
RE 2311," 30 inches in ground, and from which a:

24" Spruce bears N54°W 44.7 ft.; scribed ¼ S7 BT.

23" Spruce bears S89°E 17.0 ft.; scribed ¼ S7 BT RE 2311

Set 4"x4"x72" white painted Cedar post 1 ft. SW of pipe.  
Oregon State Board of Forestry metal location poster on  
Original 18" Hemlock BT.

Also poster on 23" Spruce BT.

Also poster on 12" Hemlock on ridge top 230.0 ft. South.

Dated June 22, 1955

Restored by Arnold G. Gibson under my direction.  
Arnold G. Gibson, Assistant Engr.



Present and witnessed by Lloyd Geraths  
Forrest Logan  
Robert Sturm